





Hecla Mining Company


- Headquartered in Coeur d'Alene, Idaho
- Modern mining technology, mitigation and reclamation
- Long lived assets with a commitment to local hiring and spending








Troy Mine Location










Development Timeline


- ROD issued for development to ASARCO 1978
 - Construction from 1978 1981
- Operated by ASARCO from 1981 1993 @ 8,500 tons/day
 - ☐ Care and maintenance from 1994 2004
- Operated by Revett from 2004 2011 @ 4,500 tons/day
 - UG collapse Dec. 2012; development 2013 2014
- Revett suspended ops in January 2015
- Hecla takes over Revett; announce reclamation June 2015.








Mining Area





UG Crushing & Ore Transport






Surface Crushing and Milling






Milling and Floatation





Tailings Transport











Regulatory Setting

Joint MT DEQ and USFS oversight because...



Private
Property, Troy
Mine Inc







Closure Plan - Goals

- Re-establish and improve wildlife habitat;
- Protect ground and surface water quality in Fairway, Stanley, and Lake Creeks;
- Protect air quality in the surrounding areas;
- Provide public access to Federal Lands; and
- Protect public health and safety by removing potential hazards.



Closure Plan – Key Details

The Rec Plan updated in 2010; EIS completed and ROD signed in 2012.

Key Elements:

- 1. Mine water management,
- 2. Tailings Impoundment Closure,
- 3. Plant site building removal, regrading, SW control,
- 4. Ventilation and secondary adit closure.



Mine Water Management


Construction of a wastewater treatment system was considered but eliminated. Water quality studies were done on the attenuation of metals in mine water at the decant ponds. These studies showed that the natural attenuation process is sufficient and that active water treatment would not be necessary.

2012 Troy Revised Reclamation Plan EIS and ROD

OK...so whats the plan??



Mine Water Quality






Mine Water Quality


Average Mine Water Quality Data During Shutdown (00' - 04')

рН	SO4 (ppm)	Hardness (ppm)	Diss Cu (ppm)	Diss As (ppm)
7.3	23	78.8	0.076	0.003 (ND)






Pipeline Route





LT Mine Water Management









Closure Plan – Key Details

The Rec Plan updated in 2010; EIS completed and ROD signed in 2012.

Key Elements:

1. Mine water management,

2. Tailings Impoundment Closure,

- 3. Plant site building removal, regrading, SW control,
- 4. Ventilation and secondary adit closure.



Tailings Impoundment Closure

> 303 surface acres; 45 acres side slope currently reclaimed





Tailings Impoundment Closure

Some regrade....







Tailings Impoundment Closure

Then cover with 18" of cover soil...amend and reveg.





Closure Plan – Key Details


The Rec Plan updated in 2010; EIS completed and ROD signed in 2012.

Key Elements:

- 1. Mine water management,
- 2. Tailings Impoundment Closure,
- 3. Plant site building removal, regrading,
- 4. Ventilation and secondary adit closure.




Plant Site Closure






Plant Site Closure





Plant Site Closure - SW






Closure Plan – Key Details

The Rec Plan updated in 2010; EIS completed and ROD signed in 2012.


Key Elements:

- 1. Mine water management,
- 2. Tailings Impoundment Closure,
- 3. Plant site building removal, regrading,
- 4. Ventilation and secondary adit closure.

Hece Adit Closure – North Portal Area



Hece Adit Closure – South Portal Area





Long Term Monitoring

Surface and ground waters; subsidence; vegetation

